

## Seam Tear-off Pliers

To test the quality of your welded seam directly on the Production line.



During the tear-off test the welded seam should not split.

- Flaky edge on the tear-off welded stripe indicates a too high welding current.
- If the welded strip breaks during the tear-off test, the welding current is too low

