

Draw Out Aid for ABM

Our SABATEC calibration crown can easily be pulled out of the welding plane with the help of two rod guides and linear roll bearings positioned left and right of the plate.

This is a simple solution to protect delicate parts such as ceramic Diabolo rolls, the lower welding arm, gas adapters from damages when spare parts need to be replaced during maintenance work.

The draw out aid is fully insulated and is compatible to all the SABATEC ABM calibration tools.

